




A x 1




B x 1




C x 1




D x 1








H x 1



E x 1




G x 3


L	 (7x40x15)	x 16
N	 Base	x 4
O	 (4x15)	x 9
P	 Screwdriver	x 1
S	 M4	x 2




1




2



3




4





5



6

